


Long units must be handled with a lifting beam at the ends



Short units must be handled with straps at the ends

Drawn by : EC	Rev : A	Date : 18-09-2012	Dwg: HOLLOWCORE HANDLING
Check by : JM	Scale : 1:40	Dwg no : Handling 2 CHC	